

RFQ 2FY20 Vendor Question 18

Please clarify interior wall type in highlighted area below. Cross section 2/A5.2 as shown going through middle wall and exterior walls per A5.1 shows the middle wall as wood framed with insulation. The foundation plan per A1.2 and lintel plan per A1.3 show the wall as CMU. **The highlighted wall should be CMU as shown in the foundation plan per A1.2 and lintel plan per A1.3**